

Oil Field Environmental Incident Summary

Incident: 20160718104908 **Date/Time of Notice:** 07/18/2016 10:49

Responsible Party: SAMSON RESOURCES COMPANY

Well Operator: SAMSON RESOURCES COMPANY

Well Name: RANCHERO 1918-2H

Field Name: AMBROSE

Well File #: 28616

Date Incident: 7/17/2016

Time Incident: 07:15

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 98

Sec: 30

Qtr:

Location Description:

Submitted By: Ross Meyer

Received By:

Contact Person: Scott Truby
2 WEST SECOND STREET
TULSA, OK 74103

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	60	Barrels	60	Barrels	59.5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/4/2016

Clean Up Concluded: 7/22/2016

Risk Evaluation:

No immediate risk, all product contained within dike.

Areal Extent:

Everything contained within dike on location.

Potential Environmental Impacts:

All oil removed, environmental impacts negligible.

Action Taken or Planned:

Spill was contained within dike. Vacuum truck utilized to remove spilled product.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/18/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.